

TABLE OF CONTENTS

VOLUME I

EXECUTIVE SUMMARY	ES-1
1.0 INTRODUCTION	1
1.1 Statement of Purpose	1
1.2 Statement of Objectives	1
1.3 RI/FS Approach	2
1.4 RI/FS Organization	3
1.4.1 Remediation Investigation	3
1.4.2 Feasibility Study	4
2.0 LOCATION AND SITE HISTORY	5
2.1 Site Location	5
2.2 Site Description	5
2.3 Description of Adjacent Properties	6
2.4 Site History	6
2.4.1 Prior Owners	8
2.5 Previous Environmental Investigations	8
3.0 PHYSICAL SETTING	11
3.1 Topography	11
3.2 Soils	11
3.3 Geology	11
3.3.1 Regional Geology	11
3.3.2 Site Geology	11
3.3.3 Groundwater Technology Investigation - 1993	12
3.3.4 Golder Investigation, 2002	12
3.3.5 Remedial Investigation, 2003	13
3.4 Hydrogeology	14
3.5 Meteorology	16
3.6 Demographics	16
3.7 Water Supply	16
3.8 Ecology	16
4.0 REMEDIAL INVESTIGATION ACTIVITES	17
4.1 Background and Existing Information Review	17
4.1.1 Topographic Map Review	17
4.1.2 Fire Insurance Maps	18
4.1.3 Environmental Database Search	18
4.1.4 Site Reconnaissance	19
4.1.5 Historical Aerial Photograph Review	23

4.2	Area Groundwater Evaluation	24
4.3	Utility Locate	24
4.4	Site Survey.....	24
4.5	Soil and Groundwater Sampling.....	25
4.5.1	Test Pit Investigations.....	26
4.5.2	GeoProbe and Hand Auger Investigations.....	27
4.5.3	Monitoring Well Drilling, Installation and Development.....	29
4.5.4	Groundwater Sampling	30
4.5.5	Sampling of Soil and Water at the Western Catch Basin	32
4.6	Water Level Measurement and Product Removal at MW-11	32
4.7	Slug Testing	32
4.8	Ecological Evaluation	33
4.9	Investigation Derived Wastes	33
4.10	Data Validation.....	33
5.0	NATURE AND EXTENT OF CHEMICAL CONSTITUENTS EXCEEDING REGULATORY CRITERIA	35
5.1	East Portion Summary of Soil and Groundwater Sample Results	35
5.1.1	Soil.....	36
5.1.2	Groundwater	36
5.2	Central Portion Summary of Soil and Groundwater Sample Results	37
5.2.1	Soil.....	37
5.2.2	Groundwater	38
5.3	West Portion Summary of Soil and Groundwater Sample Results.....	39
5.3.1	Soil.....	39
5.3.2	Groundwater	40
5.4	West Portion Catch Basin Summary of Sediment Water Sample Results.....	41
5.4.1	Catch Basin Sediment.....	41
5.4.2	Catch Basin Water	41
5.5	Site Ecological Evaluation Results	42
5.6	Remedial Investigation Conclusions.....	43
5.6.1	Summary of Remedial Investigation	43
5.6.2	Uncertainties Associated with the Data and Cleanup Criteria	43
6.0	POTENTIAL APPLICABLE OR RELEVANT AND APPROPRIATE REQUIREMENTS (ARARS).....	46
6.1	Introduction/Overview.....	46
6.2	ARARs Based on Federal Laws	46
6.3	ARARs Based on State Laws	46
7.0	REMEDIAL ACTION OBJECTIVES	50
7.1	Cleanup Goals.....	50
8.0	IDENTIFICATION AND SCREENING OF REMEDIATION TECHNOLOGIES	52
8.1	Identification and Screening of Technologies	52
8.1.1	General Response Actions.....	54
8.1.2	Institutional Controls And Monitoring	54
8.1.3	Containment.....	55

8.1.4	Removal.....	56
8.1.5	Ex-Situ Treatment.....	56
8.1.6	In-Situ Treatment.....	59
8.1.7	Disposal	59
9.0	DEVELOPMENT OF ALTERNATIVES	61
9.1	Common Elements.....	62
9.1.1	Institutional Controls	62
9.1.2	Monitoring	62
9.1.3	Excavation	63
9.2	Description of Remediation Alternatives.....	64
9.2.1	Alternative 1: No Action.....	64
9.2.2	Alternative 2: Institutional Controls and Monitoring	64
9.2.3	Alternative 3: Capping – Monitoring and Institutional Controls.....	65
9.2.4	Alternative 4: Excavation and Off-Site Landfill.....	65
9.2.5	Alternative 5: Excavation and On-Site Treatment.....	66
9.2.6	Alternative 6: Excavation and Off-Site Treatment	66
10.0	EVALUATION OF ALTERNATIVES	67
10.1	Threshold Evaluation.....	67
10.1.1	Protection of Human Health and the Environment.....	67
10.1.2	Compliance with Cleanup Standards.....	68
10.1.3	Compliance with ARARs	68
10.1.4	Provision for Compliance Monitoring.....	68
10.1.5	Summary of Threshold Evaluation	68
10.2	Use of Permanent Solutions.....	69
10.2.1	Protectiveness	69
10.2.2	Permanence.....	69
10.2.3	Costs	69
10.2.4	Effectiveness Over the Long-Term.....	70
10.2.5	Management of Short-Term Risk	70
10.2.6	Technical and Administrative Implementability	71
10.2.7	Community Acceptance.....	71
10.3	Reasonable Restoration Time Frame	71
10.4	Comparative Evaluation Methodology	72
10.5	Evaluation of Remediation Alternatives for Permanence	73
10.5.1	Evaluation of Alternative Use of Permanent Solutions the Maximum Extent Possible	73
10.5.2	Evaluation of Reasonable Restoration Time Frame	75
10.5.3	Net Benefit (Overall Non-Cost Evaluation)	76
10.5.4	Cost/Benefit Analysis and Overall Evaluation	76
10.6	Recommended Alternative.....	77
11.0	REFERENCES	78

LIST OF TABLES

Table 2-1	Summary of Decommissioned Underground Storage Tanks
Table 2-2	Site Well Construction Details
Table 3-1	Summary of Subsurface Stratigraphy
Table 3-2	Soil Physical Properties
Table 3-3	Summary of Groundwater Monitoring Well Measurements (April 1, 2003)
Table 3-4	Summary of Slug Test Results
Table 4-1	Summary of East Portion Test Pit Soil Samples
Table 4-2	Summary of Central Portion Test Pit Soil Samples
Table 4-3	Summary of East Portion GeoProbe Soil Samples
Table 4-4	Summary of Central Portion GeoProbe Soil Samples
Table 4-5	Summary of West Portion GeoProbe Soil Samples
Table 4-6	Summary of Central Portion Well Boring Soil Samples
Table 4-7	Summary of East Portion Well Groundwater Samples
Table 4-8	Summary of Central Portion Well Groundwater Samples
Table 4-9	Summary of West Portion Temporary GeoProbe Boring Groundwater Samples
Table 5-1.1	Moses Lake Maintenance Facility RIFS East Portion Soil Petroleum Hydrocarbon Results
Table 5-1.2	Moses Lake Maintenance Facility RIFS East Portion Groundwater Petroleum Hydrocarbon, Polychlorinated Biphenyls, Arsenic and Lead Results
Table 5-1.3	Moses Lake Maintenance Facility RIFS East Portion Groundwater Polynuclear Aromatic Hydrocarbon Results
Table 5-1.4	Moses Lake Maintenance Facility RIFS East Portion Groundwater Volatile Organic Compound Results (Detects Only)
Table 5-2.1	Moses Lake Maintenance Facility RIFS Central Portion Source Area Soil Petroleum Hydrocarbon, Polychlorinated Biphenyls and Lead Results
Table 5-2.2	Moses Lake Maintenance Facility RIFS Central Portion Soil Petroleum Hydrocarbon Results
Table 5-2.3	Moses Lake Maintenance Facility RIFS Central Portion Source Area Soil Polynuclear Aromatic Hydrocarbon Results
Table 5-2.4	Moses Lake Maintenance Facility RIFS Central Portion Source Area Soil Volatile Organic Compound Results (Detects Only)
Table 5-2.5	Moses Lake Maintenance Facility RIFS Central Portion Groundwater Petroleum Hydrocarbon, Polychlorinated Biphenyls, Arsenic and Lead Results
Table 5-2.6	Moses Lake Maintenance Facility RIFS Central Portion Groundwater Volatile Organic Compound Results (Detects Only)
Table 5-2.7	Moses Lake Maintenance Facility RIFS Central Portion Soil Total Organic Carbon Results
Table 5-3.1	Moses Lake Maintenance Facility RIFS West Portion Soil Petroleum Hydrocarbon Results
Table 5-3.2	Moses Lake Maintenance Facility RIFS West Portion Soil RCRA Metals Results
Table 5-3.3	Moses Lake Maintenance Facility RIFS West Portion Groundwater Petroleum Hydrocarbon, PCBs, Detected VOCs and PAH Results
Table 5-3.4	Moses Lake Maintenance Facility RIFS West Portion Groundwater RCRA Metals Results
Table 5-4.1	Moses Lake Maintenance Facility RIFS West Catch Basin Sediment Petroleum Hydrocarbon and Polychlorinated Biphenyl Results
Table 5-4.2	Moses Lake Maintenance Facility RIFS West Catch Basin Sediment Polynuclear Aromatic Hydrocarbon Results

Table 5-4.3	Moses Lake Maintenance Facility RIFS West Catch Basin Sediment RCRA Metals Results
Table 5-4.4	Moses Lake Maintenance Facility RIFS West Catch Basin Water Petroleum Hydrocarbon Results
Table 5-4.5	Moses Lake Maintenance Facility RIFS West Catch Basin Water Volatile Organic Compound Results (Detects Only)
Table 5-4.6	Moses Lake Maintenance Facility RIFS West Catch Basin Water RCRA Metals Results
Table 6-1	Federal ARARs for the Moses Lake Maintenance Facility
Table 6-2	State and Local ARARs for the Moses Lake Maintenance Facility
Table 7-1	Remediation Cleanup Goals Moses Lake Maintenance Facility
Table 8-1	Summary of Remediation Technologies Considered for the Moses Lake Maintenance Facility
Table 10-1	Evaluation Summary of Retained Remediation Alternatives
Table 10-2	Summary of Costs for Remediation Alternatives
Table 10-3	Cost Estimate for Potential Remediation Alternative for the Moses Lake Maintenance Facility
Table 10-4	Cost Benefit Analysis For Remediation Alternatives

LIST OF FIGURES

Figure 1-1	Site Location Map
Figure 1-2	Site Plan
Figure 1-3	Schematic of Site and Adjacent Properties
Figure 1-3a	Aerial Photograph and Schematic of Site and Adjacent Properties
Figure 2-1	Underground Utilities and Former USTs
Figure 2-2	Previous Investigation Sample Locations and Former USTs
Figure 3-1	Site Topography
Figure 3-2	Remedial and Previous Investigation Sample Locations
Figure 3-3	Fill Thickness
Figure 3-4	Groundwater Sampling Locations and Contour Map
Figure 5-1	Concentrations of Constituents of Concern
Figure 5-2	Constituents of Concern Areas Exceeding Cleanup Criteria
Figure 9-1	Approximate Area of Asphalt Cap for Alternative 3
Figure 9-2	Estimated Extent of Excavation for Alternatives 4, 5 and 6

LIST OF APPENDICES

Appendix A	RI Field Work Documentation
Appendix A1	Supplemental RI Field Work Documentation and Background Arsenic Groundwater Calculation
Appendix B	Physical Aquifer Properties
Appendix C	Ecological Evaluation
Appendix D	Site and Aerial Photographs
Appendix E	EDR, Inc. Reports
Appendix F	City of Moses Lake Survey Points

VOLUME II

Appendix G Data Validation and Analytical Laboratory Data Packages
Appendix H Ecology Split Data Packages